




Messmer's UV Plus Oil

UV Plus is a penetrating **deck stain, wood stain** and oil finish that beautifies and protects exterior wood, providing a natural appearance. It is ideal to protect Brazilian Hardwoods from sun and maintain color.

- Apply after installation and annually or semi-annually, as necessary to maintain color.
- Only apply ONE thin coat per application. NEVER apply more than one coat per application.
- Wipe up any excess spots with a cotton rag. There should be no shiny spots.
- Apply to clean, dry surface. Do not apply to wet boards.
- Apply with brush, rag (cotton T-shirt works well), Deck Pad or Deck Boss. Do NOT use a roller or sprayer.
- Apply in temperatures between 40-90 degrees F.
- Allow at least 12 hours to dry; it must not rain within 12 hours prior to or after application.
- Avoid any overlap: Apply to 2 or 3 boards at a time working down the length of the boards before moving on to the next 2-3 boards and repeat. Overlapping application will result in dark and/or sticky areas.
- **CAUTION:** rags/brushes WILL catch fire when exposed to prolonged sun and heat. Follow directions on can for proper disposal.



Messmer's Wood Cleaner and Brightener (Part A and B)

Messmer's Wood and Deck Cleaner and Brightener (Part A and B) powder concentrates are specially formulated to clean and brighten exterior wood decks, fences, log homes, and other exterior wood projects.

Follow the directions on the label for Part A:

1. Remove dirt and debris.
2. Dissolve 1/3 cup Part A Wood & Deck Cleaner in 1 gal of hot water, mix well.
3. Apply liberally to wood surface using garden sprayer, mop, or brush. Wait 10-15 minutes, keeping wood wet.
4. Scrub with a stiff broom or scrub brush. Rinse thoroughly with clean water.

Follow the directions on the label for Part B:

- Use after cleaning wood with Part A Wood & Deck Cleaner
- For use on stained or bare weathered wood. Not for use on painted wood.
- 1. Dissolve 1/3 cup Part B Wood & Deck Brightener in 1 gal. of hot water, mix thoroughly. Do not store in a metal container. Approx. coverage: 125 sf per gal.
- 2. Apply to cleaned and rinsed wood with a generous and even coat.
- 3. Allow 10-15 minutes for color restoration, keeping wood wet. Rinse thoroughly.
- 4. Allow wood to dry completely before applying U.V. Plus.
- Clean decks periodically, as desired, to maintain appearance.



[Brazilian Wood Depot's Cleaning/Oiling Video](#)



[Messmer's Cleaner and Brightener Video](#)